

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

WATER WELL REPORT

State of Washington

IC Site ID: **6RK** Unique Well ID
Start Card:
Water Right:

(1) OWNER: Name: **CALVARY CHAPEL (formerly FAITH PENTECOST)** Address:

(2) LOCATION OF WELL: Island: **Whidbey** Township/Range-Section: **29N/03E-34G** Parcel Number: **R32934-287-2601**

(2a) Well Address **3821 E. French Road, Clinton, WA 98236** PWS-ID: **24522H** Source: **1** PWS-Name: **Calvary Chapel of Whidbey Island**

(3) PROPOSED USE: **Domestic**

(4) TYPE OF WORK: Owner's Well Number (if more than one): **1**
Method:

(5) DIMENSIONS: Diameter of Well: inches.
Drilled: feet. Depth of Completed Well: **135** ft.

(6) CONSTRUCTION DETAILS:

Casing Installed: Diam. (in) from to (ft)

Screens: Type Zone Diam Slot from to (ft)

Surface seal:
Material: To depth: ft.

(7) PUMP: Type: **Submersible** Horsepower: **0.75**

(8) WATER LEVELS: 1 Land-surface elevation (MSL): **348.2** ft.
AvgWL Elevation: **212** Calc'd Elev: **347** ft.
Earliest Level: **135.33** ft. below toc Date: **3/26/1998**
Lastest Level: **135.33** ft. below toc Date: **3/26/1998**
Average Level: **135.30** ft. below toc Average Date: **3/26/1998**

(9) WELL TESTS:

Type	Yield	Drawdown	After	Date
Pump	10 gpm	13.2 feet	4 hours	3/26/1998

(10) WELL LOG DESCRIPTION:

Material	From BGS	From MSL	Thick
----------	----------	----------	-------

RECEIVED
APR 05 2007
DEPT. OF ECOLOGY

Work Completed: TD Elev: **212** ft. MSL

WELL CONSTRUCTOR CERTIFICATION:

Name: **Unknown**

Address:

Contractor's
Registration Number:

Remarks: **No well log available. Data obtained from PWS file. TRS changed from 29N/03E-33 after Parcel Check. No stabilization on pump test.**

Max CL: **0** Generated by the Island County
Max NO3: **12.5** Hydrogeologic Database: **3/23/2007**

Disclaimer: Data presented has been collected from a variety of sources.
Island County makes no guarantee as to the validity or accuracy of this data.
Please report any errors to the Island County Hydrogeologist



Well Tagging Form

Unique Well Tag No: APH004

RECORD VERIFICATION (check ☒ one)

- ☐ Well Report available (please attach this form to the well report and submit it to the Ecology Regional Office near you)
- ☐ Verification inconclusive
- ☒ Well Report not available

APR 05 2007

DEPT. OF ECOLOGY

WELL OWNERSHIP IF DIFFERENT FROM WELL REPORT

Name: Calvary Chapel of Whidbey Island

Street Address: 3821 E FRENCH RD

City: CLINTON

State: WA

WELL LOCATION IF DIFFERENT FROM WELL REPORT

Well Address: 3821 French Rd/R32934-287-2601

City: Clinton

County: Island

T. 29N R. 03E W.M. Sec. 34 SW 1/4 of the NE 1/4

FOR AGENCY USE ONLY

Latitude: 47 57.45966

Longitude: 122 24.46108

Elevation at land surface 348 feet / meters (circle one)

Additional Information, if available:

- ☐ Location marked on topographic map (please attach)
- ☐ Location marked on air photo (please attach)

- ☒ GPS
- ☐ Topographic Map
- ☐ Survey
- ☐ Computer generated
- ☐ Digital Altimeter
- ☐ Topographic Map
- ☒ Other: Computer Generated from DEM and GPS XY Coordinates

Tag placed and well
GPS'd by:



FOR AGENCY USE ONLY

WELL CHARACTERISTICS

Physical Description of well (size of casing, type of well, housing, etc.)

Pumphouse Is Submerged. Wellhead Is To The Right of Outside Benches Under Round Step Stone

Location of Well Identification Tag:

Was supplemental tag needed for easy of identifying well?

☐

Yes

☒

No

If yes, where was tag placed?

D	C	B	A
E	F	G	H
M	L	K	J
N	P	Q	R

SECTION: 29N/03E-34

COMMENTS:

FOR ECOLOGY WATER RESOURCES PROGRAM ONLY

Water Right #

Date Issued:

Circle One:

Application

Permit

Certificate

Claim

Exempt